

Service Bulletin

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990

MAZDA

Category S	Applicable Model/s See Below	Subject DIRT ON SEAT BELT AND ANCHOR	Bulletin No. 028/96
			Issued 06/27/96
			Revised

AFFECTED MODELS

All Models except Navajo and B-Series

DESCRIPTION

Dirt accumulating on the seat belt anchor or webbing may restrict seat belt travel over the anchor. This may cause some customers to complain that the seat belt will not retract or requires effort to pull out. Customers with this concern should have the belt inspected and serviced according to this bulletin.

SERVICE PROCEDURE

1. Clean the seat belt contact area and sash guide.


NOTE: Use a brush or cloth, lukewarm water and neutral detergent.

CAUTION: Do not use volatile solvent for cleaning, this substance may affect the seat belt strength.

2. Verify seat belt operation.

- If the seat belt is not operating smoothly, refer to the workshop manual for troubleshooting procedures.

NOTE: The seat belt will not retract smoothly while wet. Allow seat belt to dry before verifying operation.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools / equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership.