



Subject: SERVICE INFORMATION FOR KEYLESS ENTRY SYSTEM	Bulletin No: 09-018/01
	Last Issued: 12/21/2001

APPLICABLE MODEL(S)/VINS

1999-2002 Millenia
1999-2002 Protege
1999-2002 626
1999-2002 Miata
2000-2002 MPV

DESCRIPTION

It is not necessary to replace BOTH the keyless entry unit and the transmitter when repairing the keyless entry systems.

If there are any concerns with the keyless entry system, then first determine which of the parts is inoperative, and **replace only the failed part.**

REPAIR PROCEDURE

For troubleshooting the keyless entry system, refer to the appropriate Workshop Manual (section 09) for Symptom Troubleshooting the Keyless Entry System.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership.